

**Illinois Commerce Commission**  
**Pipeline Safety**  
**Exit Meeting Documentation Form**

<b>Operator:</b>	AMEREN ILLINOIS COMPANY
<b>Inspection Unit(s):</b>	Galesburg, Kewanee
<b>Date of Meeting:</b>	10/10/2013
<b>Pipeline Safety Analyst:</b>	Donald Hankins, Kevin Hecker
<b>Exit Meeting Contact:</b>	Fred McMaster

**Issues Identified/Amendments/Probable Violations:**

**ISSUE(S) FOUND:**

NO ISSUES FOUND.

**ISSUE(S) CORRECTED:**

NO ISSUES CORRECTED.

**NOTICE OF AMENDMENT(S) FOUND:**

NO NOAs FOUND.

**NOA(S) CORRECTED:**

NO NOAs CORRECTED.

**NOTICE OF PROBABLE VIOLATION(S) FOUND:**


NO NOPVs FOUND.

**NOPV(S) CORRECTED:**

2011-V001-00037 - Examination is being completed twice per year on the pipe in question. A leak survey is also being conducted as part of this examination. Ameren has long-term plans to re-bury the pipe within the next 2 years.

2011-V001-00054 - The Davis Regulating Station that was written up for atmospheric corrosion has been retired. A new station with Mooney Regulators has been installed. The station piping is painted and no atmospheric corrosion was found.

Pipeline Safety Analyst Signature:



Operator Representative Signature:

